

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-024470**Date Inspected:** 04-Jun-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Mr. Lu Hua Jie**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Orthotropic Box Girder (OBG)**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Shailesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Chang xing Island in Shanghai, China. QA observed and/or found the following:

BAY 14:

This QA Inspector performed randomly Visual Inspection and Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL-6027 (UT) report for this date. The member is identified as OBG Segment 14 East. The weld designations reviewed are as follows.

SEG3019P-006, 230, 231, 237, 243, 245, 239, 241, 236, 244, 242, 238, 240

SEG3019D-1-327, 329, 331,

SEG3019E-1-411, 413, 415

SEG3019M-256, 257, 258

SEG3019R-124, 126, 123, 131, 127

SEG3019T-127, 119, 121, 125, 129, 126, 118, 120, 124, 128

SEG3019V-070, 087, 088, 085, 084, 083

SEG3019S-151, 149, 150, 148, 154, 155, 152, 153

NDT Notification No-09356

This QA Inspector randomly observed the following work in progress.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

SMAW Process:


This QA Inspector observed ZPMC qualified welding personnel identified as 044779 Perform Shielded Metal Arc Welding (SMAW) on OBG Segment 14 East Edge panel I rib joint. Joint identified as SEG3019J-066, 060. ZPMC QC Identified as Zhu Yuan Yuan. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-P-2214-Tc-U4b-FCM-1. For more information see below attached picture number 1.

This QA Inspector observed ZPMC qualified welding personnel identified as 216086 Perform Shielded Metal Arc Welding (SMAW) on OBG Segment 14 East Edge panel I rib joint. Joint identified as SEG3019J-068, 062. ZPMC QC Identified as Zhu Yuan Yuan. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-P-2214-Tc-U4b-FCM-1.

Repair welding, SMAW Process:

This QA Inspector observed ZPMC qualified welding personnel identified as 501946 Perform Shielded Metal Arc Welding (SMAW) on OBG Segment 14 East inside near panel point 126.5. VT repair on some locations. ZPMC QC Identified as Zhu Yuan Yuan with Temporary welding repair report. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-345-SMAW-2G 3G (2F, 3F)-FCM-Repair-1.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.



Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang: 15000422372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By: Gaikwad,Shailesh

Quality Assurance Inspector

Reviewed By: Patterson,Rodney

QA Reviewer